



PURPOSE

To connect slickline to the tool string.

ASSEMBLY PARTS

1. Body
2. Spring
3. Thimble
4. Spool

OPERATION

Thread line through top of rope socket, spring, and thimble, wrap line around spool and back over itself several times to form a knot.
(care should be taken to form the line around the spool and not bend or kink the line as this may create a weak spot in line and lead to failure).

| Nominal Size | | 1.00" | 1.25" | 1.50" |
|-------------------------|-----------|----------------|---------------|---------------|
| Assembly Number | | 0101RS100A0 | 0101RS125A1 | 0101RS150A1 |
| Item | Part Name | | | |
| 1 | Body | 0101RS10001 | 0101RS12501 | 0101RS15001 |
| 2 | Spring | n/a | 0101RS09204 | 0101RS09204 |
| 3 | Thimble | 0101RS10005 | 0101RS09205 | 0101RS09205 |
| 4 | Spool | 0101RS10006 | 0101RS09206 | 0101RS09206 |
| Lower Thread Connection | | 0.625 - 11 UNC | 0.938 - 10 UN | 0.938 - 10 UN |
| Max O.D. | | 1.00" | 1.25" | 1.50" |
| Fishneck size | | 1.00" | 1.18" | 1.375" |

| Nominal Size | | 1.75" | 1.87" | 2.12" |
|-------------------------|-----------|---------------|---------------|---------------|
| Assembly Number | | 0101RS175A1 | 0101RS187A1 | 0101RS212A1 |
| Item | Part Name | | | |
| 1 | Body | 0101RS17501 | 0101RS18701 | 0101RS21201 |
| 2 | Spring | 0101RS09204 | 0101RS09204 | 0101RS09204 |
| 3 | Thimble | 0101RS09205 | 0101RS09205 | 0101RS09205 |
| 4 | Spool | 0101RS09206 | 0101RS09206 | 0101RS09206 |
| Lower Thread Connection | | 1.062 - 10 UN | 1.062 - 10 UN | 1.062 - 10 UN |
| Max O.D. | | 1.75" | 1.875" | 2.12" |
| Fishneck size | | 1.75" | 1.75" | 1.75" |

When ordering please specify part name and size. Call us Toll Free: 1-800-438-0061